



Photo 1

Overview of existing roof below the tracks.



Photo 2

Overview of existing roof below the tracks.



Photo 3

Overview of existing roof below the tracks.



Photo 4

Overview of existing roof below the tracks.



Photo 5

Rising wall at penthouse providing access to the platform above the roof.



Photo 6

Rising masonry building wall at the east side of the roof.



Photo 7

Existing edge condition at the south side of the roof below the tracks. Condition at north side is similar.



Photo 8

Existing construction to remain above the west side of the roof below the track (left side of photo is active platform, right side of photo is the canopy above the bus terminal – not in contract)



Photo 9

Overview of the west side of the roof below the tracks.



Photo 10

Existing edge condition at the west side of the roof below the tracks.



Photo 11

Exploratory cut in existing roofing system at the roof below the track.



Photo 12

Typical steel column penetration.



Photo 13

Vent pipe penetration through the roof below the tracks.



Photo 14

Typical roof drain with metal screen cover adjacent to column at the roof below the tracks. Note the exploratory opening visible in the photo adjacent to the roof drain.