

Notes on Drain Pipes:

- SE drain (1 on graphic) found to be clogged just above the level of the street, probably just above an elbow that leads out towards the street, approximately 60' down from the roof deck.
- We have a few videos of the scoping and we can make these available in the addendum via a dropbox link
- Brownstone is on National Register of Historic Places. Plans must be reviewed/approved by SPHO
- Assumptions:
 - Some small demo at base of the building
 - Possible demo of sidewalk and main entrance steps where drain goes from building to street
 - Restoration of all building and site elements